

阅读申明

- 1.本站收集的数据手册和产品资料都来自互联网，版权归原作者所有。如读者和版权方有任何异议请及时告之，我们将妥善解决。
- 2.本站提供的中文数据手册是英文数据手册的中文翻译，其目的是协助用户阅读，该译文无法自动跟随原稿更新，同时也可能存在翻译上的不当。建议读者以英文原稿为参考以便获得更精准的信息。
- 3.本站提供的产品资料，来自厂商的技术支持或者使用者的心得体会等，其内容可能存在描述上的差异，建议读者做出适当判断。
- 4.如需与我们联系，请发邮件到marketing@iczoom.com，主题请标有“数据手册”字样。

Read Statement

1. The datasheets and other product information on the site are all from network reference or other public materials, and the copyright belongs to the original author and original published source. If readers and copyright owners have any objections, please contact us and we will deal with it in a timely manner.
2. The Chinese datasheets provided on the website is a Chinese translation of the English datasheets. Its purpose is for reader's learning exchange only and do not involve commercial purposes. The translation cannot be automatically updated with the original manuscript, and there may also be improper translations. Readers are advised to use the English manuscript as a reference for more accurate information.
3. All product information provided on the website refer to solutions from manufacturers' technical support or users the contents may have differences in description, and readers are advised to take the original article as the standard.
4. If you have any questions, please contact us at marketing@iczoom.com and mark the subject with "Datasheets" .



May 12th , 2015

Re: DIP40 and DIP20 supply situation; vide discontinuation notice 201406022DN, July 2014

Dear Customer,

This letter is to apprise you of the current situation involving supply disruption of NXP microcontrollers in the DIP40 and DIP20 packages.

In the discontinuation notice 201406022DN issued by NXP on July 1st 2014, all DIP20 and DIP40 microcontrollers were earmarked for product discontinuation with a last time buy date of 31st December 2014 and a last time ship date of 31st March 2015.

As of April 2015, NXP was unable to manufacture DIP40 and DIP20 packaged parts due to non-operational mold equipment. Further, NXP has confirmed that the recovery of this equipment and resumption of production using this equipment is not possible.

Currently, NXP is working on evaluating various options including third party manufacturing capability to meet last time buy orders.

Please accept our sincere apologies for this supply-related predicament. We value your relationship and rest assured that we are evaluating every possibility to resume supply of parts.

We will update you about the results of our evaluation by June 15th 2015. In the meantime, I welcome you to get in touch with your regional NXP contact with questions related to specific products and supply.

Thank you,



Jim Trent
NXP Semiconductors
VP & GM, Microcontrollers
411 E. Plumeria Drive,
San Jose, CA 95134