

阅读申明

- 1.本站收集的数据手册和产品资料都来自互联网，版权归原作者所有。如读者和版权方有任何异议请及时告之，我们将妥善解决。
- 2.本站提供的中文数据手册是英文数据手册的中文翻译，其目的是协助用户阅读，该译文无法自动跟随原稿更新，同时也可能存在翻译上的不当。建议读者以英文原稿为参考以便获得更精准的信息。
- 3.本站提供的产品资料，来自厂商的技术支持或者使用者的心得体会等，其内容可能存在描述上的差异，建议读者做出适当判断。
- 4.如需与我们联系，请发邮件到marketing@iczoom.com，主题请标有“数据手册”字样。

Read Statement

1. The datasheets and other product information on the site are all from network reference or other public materials, and the copyright belongs to the original author and original published source. If readers and copyright owners have any objections, please contact us and we will deal with it in a timely manner.
2. The Chinese datasheets provided on the website is a Chinese translation of the English datasheets. Its purpose is for reader's learning exchange only and do not involve commercial purposes. The translation cannot be automatically updated with the original manuscript, and there may also be improper translations. Readers are advised to use the English manuscript as a reference for more accurate information.
3. All product information provided on the website refer to solutions from manufacturers' technical support or users the contents may have differences in description, and readers are advised to take the original article as the standard.
4. If you have any questions, please contact us at marketing@iczoom.com and mark the subject with "Datasheets" .



Customer Information Notification

2013060171

Issue Date: 02-Jul-2013
Effective Date: 06-Jul-2013

Here's your personalized quality information concerning products from NXP.

For detailed information we invite you to [view this notification online](#)



QUALITY

Management Summary

This Notification is about the change of resin hardener of two (2) Henkel mold compounds used in NXP product packaging, due to discontinued supply of the resin hardener by original supplier.

Change Category

Wafer Fab process	Assembly Process	Product Marking	Design
Wafer Fab materials	Assembly Materials	Electrical spec./Test coverage	Mechanical Specification
Wafer Fab location	Assembly Location	Test Location	Packing/Shipping/Labeling

Change of resin hardener of two Henkel mold compounds used in NXP products

Information Notification

This is to inform about a minor change in Henkel mold compounds used in NXP product packaging. Henkel announced a change of supply source for the resin hardeners, due to discontinued supply by original supplier. They will be replaced by another supplier, with materials of same composition and same functionality. The affected Henkel mold compound series are GR646 and KL1000-3AP. An extended characterization and qualification has been carried out with all results pass. There is no change in product reliability and functionality.

Why do we issue this Information Notification

The NXP products on the attached list are affected by this change.

Identification of Affected Products

Backwards traceable via assembly week-code in the marking on the products.

Impact

no impact to the product's functionality anticipated.

Data Sheet Revision

No impact to existing datasheet

Disposition of Old Products

Existing inventory will be shipped until depleted

Additional information

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please [contact NXP "Global Quality Support Team"](#).

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.
Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

A global semiconductor company with operations in more than 25 countries, NXP posted unaudited revenue of \$4.36 billion in 2012.

You have received this email because you are a designated contact or subscribed to NXP's Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[View Notification](#)

[Subscription](#)

[Support](#)

[NXP](#) | [Privacy Policy](#) | [Terms of Use](#)

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.